



Part no.: 426128
AC-MLC-END
Connector set



Figure can vary

Contents

- Set consists of
- Technical data
- Notes

Part no.: 426128 – AC-MLC-END – Connector set

Set consists of

	Quantity	Part no.	Designation	Article	Description
	1	426127	AC-MLC-HR-END	Host receiver termination	Connection 1: Connector, M12, Axial, Male, 8 -pin Connector, encoding: A-coded Degree of protection: IP 67
	1	426126	AC-MLC-HT-END	Host transmitter termination	Connection 1: Connector, M12, Axial, Male, 8 -pin Connector, encoding: A-coded Degree of protection: IP 67

Technical data

Basic data

Application	Alignment and setup aid for MLC 520 Host versions
Suitable for	MLC 500 host transmitter safety light curtains MLC 520 host receiver safety light curtains

Certifications

Degree of protection	IP 67
----------------------	-------

Classification

Customs tariff number	85366990
eCl@ss 8.0	27069190
eCl@ss 9.0	27069190
ETIM 5.0	EC001578
ETIM 6.0	EC001578

Notes

WARNING!

Risk of injury due to insufficient safety distance

- Integration of a Guest device results in an increase in reaction time. For this reason, a large safety distance must be allowed for.
- For further information, refer to calculation of the safety distance in the connecting and operating instructions.

Part no.: 426128 – AC-MLC-END – Connector set

WARNING!

Risk of injury due to missing stepping behind protection

- If the terminating plugs are used, take appropriate measures to ensure that it is not possible to step behind the safety light curtain.

WARNING!

Risk of injury due to unforeseeable machine behavior

- Changes made to the protective device can lead to unforeseeable machine behavior.
- After making changes, have the protective device checked by a qualified person.

NOTE

- Refer to the MLC 520 Host connecting and operating instructions.